



Project:

Client: **TRANSFLUID S.r.l.**
Via Guido Rossa, 4
Gallarate (VA)

Office: **MILAN**

Client's Order Number:

Date: **04 March 2016**

Order Status: **COMPLETE**

Inspection Dates

First: **31 July 2015**

Final: **18 February 2016**

This certificate is issued to **TRANSFLUID S.r.l.**

To certify that Mr. M. RICCARDI and Mr. D. MAGNAGHI surveyors to this Society did, at their request, attend their Works at Gallarate – Varese, for the purpose of inspecting the following materials:

Description: **No 2 MULTIPLE PUMP DRIVE Type MPD22**
Rating : **720KW at 2250 rpm**
Serial Number: **M1053 and M1054**

The following inspection and tests were satisfactorily carried out against order LR Rules and applicable specifications requirements and drawings approved by LR Southampton Office with DAD ENG 22546603 ISSUE NUMBER 1 on 12 January 2016:

- Basic material identification against mill sheets
- Review basic material chemical analysis (declared by Manufacturers).
- Select check test samples
- Witness mechanical tests
- Check dimensions
- Witness functional test
- Final documentation review

For identification and acceptance purpose the above material was hard stamped: LR MR MLN1580762 in addition to the manufacturer marking required.

04 March 2016



M. RICCARDI
Surveyor to Lloyd's Register EMEA

a member of the Lloyd's Register group

Lloyd's Register Group Limited, its affiliates and subsidiaries and their respective officers, employees or agents are, individually and collectively, referred to in this clause as 'Lloyd's Register'. Lloyd's Register assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant Lloyd's Register entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract